

SDI Diagnostics Inc – Printer Compatibility List

The following printers have been tested and have been found to be compatible with our Spirometers.

| l- | | |
|--|---|--|
| HP-2 Driver For Spirolab II For Spirolab For SBG For Spirobank For SBO MUST HAVE A PARALLEL PORT | *** Not Tested *** Astra 100/200/300 AstraTouch Printers in this column have the correct driver and should work but have not been tested | Astra 100/200/300/AstraTouch ** To work the printer language must be PCL 3 (except GUI), PCL5e/PCL6 ***Astra 100/200/300 Only with 1.17 Firmware or higher works with PCL3 *** |
| Compatible Printers | Should work | Compatible Printers |
| HP-500 Inkjet | HP-2420DN | Samsung ML-2851ND |
| HP-610 Inkjet | HP-1320TN | Samsung ML1450 |
| HP-632 Inkjet | HP-4250N | Brother HL-2170W |
| HP-648 Inkjet | Brother HL-5240 | OKI B2400N Laser |
| HP-697 Inkjet | Brother HL-5250 DN | OKI B2400 Laser |
| HP-895 Inkjet | Brother HL-5250 DNT | Dell – 1710 Laser |
| HP-930 Inkjet | Brother HL-5280DW | Dell – P1500 |
| HP-932 Inkjet | Brother HL-6050 | Brother- HL-5140 Laser |
| HP-3820 Inkjet | Brother HL-6050DN | Brother- HL-2070N Laser |
| HP-5550 Inkjet | Brother HL-7050 | Brother- HL-1440 Laser |
| HP-5560 Inkjet | Brother HL-7050DN | HP-5650 Inkjet |
| HP-5650 Inkjet | Samsung ML 4551 NDR | HP-5560 Inkjet |
| Brother- HL-1440 Laser | Dell 1720 DN | HP-5550 Inkjet |
| Brother- HL-2070N Laser | Canon ImageWriter 3230 | HP-3820 Inkjet |
| Brother- HL-5140 Laser | Konica Minolta Bizhub 20P | HP-932 Inkjet |
| Dell – P1500 | | HP-930 Inkjet |
| Dell – 1710 Laser | | HP-895 Inkjet |
| OKI B2400 Laser | | HP Officejet Pro 8000 ***Requires Firmware Version 1.17 or Higher to Function |
| OKI B2400N Laser | | HP Officejet 4500 ***Requires Firmware Version 1.17 or Higher to Function |
| | | Samsung ML-2955ND |
| | | HP Officejet 4620 Color ***Requires Firmware Version 1.17 or Higher to Function |