



## SDI Diagnostics Inc – Printer Compatibility List

The following printers have been tested and have been found to be compatible with our Spirometers.

<b>HP-2 Driver</b> For Spirolab II For Spirolab For SBG For Spirobank For SBO <b>MUST HAVE A PARALLEL PORT</b>	<b>*** Not Tested ***</b> <b>Astra 100/200/300</b> <b>AstraTouch</b>  <b>Printers in this column have</b> <b>the correct driver and should</b> <b>work but have not been tested</b>	<b>Astra 100/200/300/AstraTouch</b>  <b>** To work the printer language</b> <b>must be PCL 3 (except GUI),</b> <b>PCL5e/PCL6</b>  <b>***Astra 100/200/300 Only with</b> <b>1.17 Firmware or higher works</b> <b>with PCL3 ***</b>
<b>Compatible Printers</b>	<b>Should work</b>	<b>Compatible Printers</b>
HP-500 Inkjet	HP-2420DN	Samsung ML-2851ND
HP-610 Inkjet	HP-1320TN	Samsung ML1450
HP-632 Inkjet	HP-4250N	Brother HL-2170W
HP-648 Inkjet	Brother HL-5240	OKI B2400N Laser
HP-697 Inkjet	Brother HL-5250 DN	OKI B2400 Laser
HP-895 Inkjet	Brother HL-5250 DNT	Dell – 1710 Laser
HP-930 Inkjet	Brother HL-5280DW	Dell – P1500
HP-932 Inkjet	Brother HL-6050	Brother- HL-5140 Laser
HP-3820 Inkjet	Brother HL-6050DN	Brother- HL-2070N Laser
HP-5550 Inkjet	Brother HL-7050	Brother- HL-1440 Laser
HP-5560 Inkjet	Brother HL-7050DN	HP-5650 Inkjet
HP-5650 Inkjet	Samsung ML 4551 NDR	HP-5560 Inkjet
Brother- HL-1440 Laser	Dell 1720 DN	HP-5550 Inkjet
Brother- HL-2070N Laser	Canon ImageWriter 3230	HP-3820 Inkjet
Brother- HL-5140 Laser	Konica Minolta Bizhub 20P	HP-932 Inkjet
Dell – P1500		HP-930 Inkjet
Dell – 1710 Laser		HP-895 Inkjet
OKI B2400 Laser		HP Officejet Pro 8000 <b>***Requires Firmware Version 1.17 or Higher to Function</b>
OKI B2400N Laser		HP Officejet 4500 <b>***Requires Firmware Version 1.17 or Higher to Function</b>
		Samsung ML-2955ND
		HP Officejet 4620 Color <b>***Requires Firmware Version 1.17 or Higher to Function</b>

Other newer models from these companies may be compatible but have not been tested.